

DIN EN 16016-3:2012-12 (E)

Non destructive testing - Radiation methods - Computed tomography - Part 3: Operation and interpretation

| Contents | | Page |
|-----------------------|--|-------------|
| Foreword | | 3 |
| Introduction | | 4 |
| 1 | Scope | 5 |
| 2 | Normative references | 5 |
| 3 | Terms and definitions | 5 |
| 4 | Operational procedure | 5 |
| 4.1 | General | 5 |
| 4.2 | CT system set-up | 5 |
| 4.2.1 | General | 5 |
| 4.2.2 | Geometry | 5 |
| 4.2.3 | X-ray source | 6 |
| 4.2.4 | Detector | 6 |
| 4.3 | Reconstruction parameters | 7 |
| 4.4 | Visualisation | 7 |
| 4.5 | Analysis and interpretation of CT images | 7 |
| 4.5.1 | General | 7 |
| 4.5.2 | Feature testing/defect testing | 7 |
| 4.5.3 | Dimensional testing | 8 |
| 5 | Requirements for acceptable results | 10 |
| 5.1 | Image quality parameters | 10 |
| 5.1.1 | Contrast | 10 |
| 5.1.2 | Noise | 12 |
| 5.1.3 | Signal to noise ratio | 12 |
| 5.1.4 | Contrast to noise ratio | 12 |
| 5.1.5 | Spatial resolution | 13 |
| 5.2 | Suitability of testing | 15 |
| 5.3 | CT examination interpretation and acceptance criteria | 15 |
| 5.4 | Records and reports | 15 |
| 5.5 | Artefacts | 16 |
| 5.5.1 | General | 16 |
| 5.5.2 | Beam hardening artefacts | 16 |
| 5.5.3 | Edge artefacts | 17 |
| 5.5.4 | Scattered radiation | 18 |
| 5.5.5 | Instabilities | 18 |
| 5.5.6 | Ring artefacts | 18 |
| 5.5.7 | Centre of rotation error artefacts | 19 |
| 5.5.8 | Motion artefacts | 20 |
| 5.5.9 | Artefacts due to an insufficient number of projections | 21 |
| 5.5.10 | Cone beam artefacts | 21 |
| Annex A (informative) | Spatial resolution measurement using line pair gauges | 23 |
| A.1 | Line pair gauges | 23 |
| A.2 | Principle of measurement | 24 |
| Bibliography | | 27 |