

# ISO 7539-11:2013-04 (E)

## Corrosion of metals and alloys - Stress corrosion cracking - Part 11: Guidelines for testing the resistance of metals and alloys to hydrogen embrittlement and hydrogen-assisted cracking

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Factors to be considered in hydrogen embrittlement and hydrogen-assisted cracking testing .....</b>	<b>1</b>
3.1	Dynamic plastic straining .....	1
3.2	Test time and hydrogen uptake .....	2
3.3	Temperature .....	2
<b>4</b>	<b>Selection of test method .....</b>	<b>3</b>
4.1	General .....	3
4.2	Specimen type .....	3
4.3	Test duration .....	3
4.4	Load form .....	8
4.5	Pre-charging and hydrogen effusivity .....	12
4.6	Testing of welds .....	12
<b>5</b>	<b>Post-test evaluation .....</b>	<b>13</b>
Bibliography .....		15