

ISO 7539-11:2013-04 (E)

Corrosion of metals and alloys - Stress corrosion cracking - Part 11: Guidelines for testing the resistance of metals and alloys to hydrogen embrittlement and hydrogen-assisted cracking

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Factors to be considered in hydrogen embrittlement and hydrogen-assisted cracking testing	1
3.1	Dynamic plastic straining	1
3.2	Test time and hydrogen uptake	2
3.3	Temperature	2
4	Selection of test method	3
4.1	General	3
4.2	Specimen type	3
4.3	Test duration	3
4.4	Load form	8
4.5	Pre-charging and hydrogen effusivity	12
4.6	Testing of welds	12
5	Post-test evaluation	13
Bibliography		15