

ISO/TS 16190:2013-07 (E)

Footwear - Critical substances potentially present in footwear and footwear components - Test method to quantitatively determine polycyclic aromatic hydrocarbons (PAH) in footwear materials

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Principle	1
4	Chemicals	1
5	Apparatus and materials	2
6	Procedure	3
6.1	Preparation of standard solutions	3
6.2	Sample preparation	4
6.3	Extraction	5
6.4	Determination	5
7	Quantification	5
8	Performance of the method	5
9	Test report	6