

ISO 23380:2013-09 (E)

Selection of methods for the determination of trace elements in coal

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Abbreviations	1
5	Discussion of methods	2
5.1	General	2
5.2	Arsenic and selenium	2
5.3	Boron	2
5.4	Antimony, beryllium, cadmium, chromium, cobalt, copper, lead, manganese, molybdenum, nickel, thallium, vanadium, zinc, thorium, and uranium	2
5.5	Chlorine	3
5.6	Fluorine	3
5.7	Mercury	3
6	Use of certified reference materials	3
7	Calculation of results	4
8	Sensitivity	4
9	Reporting of results	5
10	Precision	6
11	Test report	6
Annex A (informative) Scheme of analysis for trace elements		7
Annex B (informative) Alternative dissolution procedures for coal		8
Bibliography		9