

ISO Guide 33:2015-02 (E)

Reference materials - Good practice in using reference materials

Contents	Page
Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
4 Symbols	3
5 Conventions	3
6 RMs and their role in measurement	4
6.1 Common applications of RMs	4
6.2 Property values	6
6.2.1 General	6
6.2.2 Specification of the property	6
6.3 Uncertainty statement	6
6.4 Traceability statement	8
7 Handling of RMs and CRMs	9
8 Assessment of precision	9
8.1 General	9
8.2 Number of replicate measurements	9
8.3 Requirements with respect to the RM	10
8.4 Measurement	11
8.5 Data treatment	11
8.6 Calculation and assessment of precision	12
9 Bias assessment	12
9.1 General	12
9.2 Approach to bias checking	13
9.3 Utilizing bias data	13
10 Calibration	14
10.1 General	14
10.2 Establishing metrological traceability	15
10.3 Calibration models	15
11 Assigning values to other materials	15
11.1 General	15
11.2 Pure materials	16
11.3 Gravimetry and volumetry	17
12 Conventional scales	18
12.1 General	18
12.2 pH-scale	19
12.3 Octane number	19

13	Selection of CRMs and RMs	20
13.1	General	20
13.2	Selection of a CRM	20
13.3	Selection of RMs	23
13.4	Relevance to the measurement system	23
Annex A (informative)	Key characteristics of a reference material with respect its common applications	25
Annex B (informative)	Calibration models and associated uncertainty models	26
Annex C (informative)	Decision errors	29
Bibliography		30