

# ISO 23277:2015-03 (E)

## Non-destructive testing of welds - Penetrant testing - Acceptance levels

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Testing parameters .....</b>	<b>2</b>
<b>4.1</b>	<b>General .....</b>	<b>2</b>
<b>4.2</b>	<b>Sensitivity .....</b>	<b>2</b>
<b>4.3</b>	<b>Surface condition .....</b>	<b>2</b>
<b>4.4</b>	<b>Process and technique .....</b>	<b>2</b>
<b>5</b>	<b>Acceptance levels .....</b>	<b>2</b>
<b>5.1</b>	<b>General .....</b>	<b>2</b>
<b>5.2</b>	<b>Evaluation of indications .....</b>	<b>3</b>
<b>5.3</b>	<b>Removal of imperfections .....</b>	<b>3</b>
<b>Annex A (informative) Recommended testing parameters .....</b>		<b>4</b>