

ISO 18554:2016-03 (E)

Surface chemical analysis - Electron spectroscopies - Procedures for identifying, estimating and correcting for unintended degradation by X-rays in a material undergoing analysis by X-ray photoelectron spectroscopy

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Terms and definitions	1
3	Symbols and abbreviated terms	1
4	Sample degradation	2
4.1	Causes of degradation	2
4.2	Sample degradation	3
4.3	Measurements for identifying, and correcting for, degradation	3
4.3.1	Recognition of degradation	3
4.3.2	The first survey scan	3
4.3.3	The detail scans	4
4.3.4	The final survey scan	4
4.3.5	Inverting the order of acquisition for unstable compounds	4
4.3.6	Check for degradation	4
4.3.7	Deduce the undegraded intensity	4
4.4	Assessing the likelihood of degradation	6
4.4.1	Determining the value of AZ	6
4.5	Reporting degradation	6
4.6	Suggested procedures for minimising degradation	6
4.7	Influence of contamination	7
4.7.1	Contamination formation during spectrum acquisition	7
4.7.2	Reporting contamination	7
	Annex A (informative) Materials reported to degrade during analysis	8
	Annex B (informative) Examples of degradation	9
	Annex C (informative) Compensation for formation of a contamination layer	14
	Bibliography	16