

## Nanotechnologies - Characterization of cellulose nanocrystals

---

Contents	Page
Foreword .....	iv
Introduction .....	v
1 Scope .....	1
2 Terms and definitions .....	1
3 Symbols and abbreviated terms .....	2
4 Production of cellulose nanocrystals (CNCs) .....	3
5 Composition .....	6
5.1 Chemical composition .....	6
5.2 Surface functional groups .....	7
5.2.1 Determination of sulfate half-esters .....	7
5.2.2 Determination of carboxylic acids .....	11
5.3 Degree of polymerization .....	12
5.4 Crystallinity .....	13
5.4.1 General .....	13
5.4.2 X-ray diffraction .....	14
5.4.3 Nuclear magnetic resonance .....	16
5.4.4 Vibrational spectroscopy .....	18
5.4.5 Crystallinity measurements for CNCs .....	18
5.5 Moisture content .....	20
5.6 Contaminants .....	20
5.6.1 General .....	20
5.6.2 Residual impurities derived from cellulosic biomass .....	21
5.6.3 Metal ions .....	21
5.6.4 Detection of contaminants by X-ray photoelectron spectroscopy .....	21
6 CNC Morphology .....	22
6.1 Distributions of length and cross-section from microscopy .....	22
6.1.1 General .....	22
6.1.2 Electron microscopy .....	23
6.1.3 Atomic force microscopy .....	25
6.1.4 Image analysis considerations .....	27
6.1.5 Microscopy size distributions for CNCs .....	27
6.2 Size measurement by dynamic light scattering (DLS) .....	31
7 CNC Surface characteristics .....	33
7.1 Specific surface area .....	33
7.2 Surface charge .....	34
8 Miscellaneous .....	35
8.1 Thermal properties .....	35
8.2 Viscosity .....	38
9 Concluding comments .....	38
Bibliography .....	40