

# ISO 16700:2016-08 (E)

## Microbeam analysis - Scanning electron microscopy - Guidelines for calibrating image magnification

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Image magnification .....</b>	<b>3</b>
4.1	Scale marker .....	3
4.2	Expressing magnification .....	3
<b>5</b>	<b>Reference material .....</b>	<b>3</b>
5.1	General .....	3
5.2	Requirements for CRM .....	4
5.3	Pitch patterns on CRM .....	4
5.4	Storage and handling .....	4
<b>6</b>	<b>Calibration procedures .....</b>	<b>5</b>
6.1	General .....	5
6.2	Mounting CRM .....	5
6.3	Setting SEM operation conditions for calibration .....	5
6.4	Image recording .....	6
6.5	Measurement of image .....	6
6.6	Calibration of magnification and scale marker .....	7
6.6.1	General .....	7
6.6.2	Magnification .....	7
6.6.3	Scale marker .....	7
<b>7</b>	<b>Accuracy of image magnification and scale marker .....</b>	<b>8</b>
<b>8</b>	<b>Calibration report .....</b>	<b>9</b>
8.1	General .....	9
8.2	of calibration report .....	9
<b>Annex A (informative) Reference materials for magnification .....</b>		<b>11</b>
<b>Annex B (informative) Parameters that influence the resultant magnification of an SEM .....</b>		<b>13</b>
<b>Annex C (informative) Uncertainties in magnification measurements .....</b>		<b>15</b>
<b>Annex D (informative) Example of a test report .....</b>		<b>16</b>
<b>Bibliography .....</b>		<b>18</b>