

ISO 16700:2016-08 (E)

Microbeam analysis - Scanning electron microscopy - Guidelines for calibrating image magnification

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Image magnification	3
4.1	Scale marker	3
4.2	Expressing magnification	3
5	Reference material	3
5.1	General	3
5.2	Requirements for CRM	4
5.3	Pitch patterns on CRM	4
5.4	Storage and handling	4
6	Calibration procedures	5
6.1	General	5
6.2	Mounting CRM	5
6.3	Setting SEM operation conditions for calibration	5
6.4	Image recording	6
6.5	Measurement of image	6
6.6	Calibration of magnification and scale marker	7
6.6.1	General	7
6.6.2	Magnification	7
6.6.3	Scale marker	7
7	Accuracy of image magnification and scale marker	8
8	Calibration report	9
8.1	General	9
8.2	of calibration report	9
Annex A (informative) Reference materials for magnification		11
Annex B (informative) Parameters that influence the resultant magnification of an SEM		13
Annex C (informative) Uncertainties in magnification measurements		15
Annex D (informative) Example of a test report		16
Bibliography		18