

DIN 50100:2016-12 (E)

Load controlled fatigue testing - Execution and evaluation of cyclic tests at constant load amplitudes on metallic specimens and components

Contents	Page
Foreword	4
Introduction	5
1 Scope	6
2 Normative references	6
3 Symbols and abbreviations	6
4 S-N curve (Wöhler curve)	12
5 Load types	17
6 Shape of the specimens and specimen manufacturing	19
7 Test setup	21
8 Test procedure	22
8.1 General	22
8.2 High cycle fatigue	22
8.2.1 General	22
8.2.2 Pearl string method	26
8.2.3 Load level method	33
8.3 Long life fatigue strength	41
8.3.1 General	41
8.3.2 Staircase method	44
9 Test evaluation	50
9.1 General	50
9.2 High cycle fatigue	51
9.2.1 General	51
9.2.2 Pearl string method	51
9.2.3 Load level method	54
9.3 Evaluating long life fatigue strength	56
9.3.1 General	56
9.3.2 Staircase method	56
9.4 Number of cycles at knee point and course of the S-N curve in the long life fatigue regime	58
9.5 S-N curve for failure probabilities other than 50 %	59
10 Documentation	60
10.1 General	60
10.2 Material	61
10.3 Specimen (material sample or component)	61
10.4 Test setup	62
10.5 Test procedure	62
10.6 Test evaluation	62
10.7 S-N curve (Wöhler curve)	63
Annex A (normative) Pearl string method: Determination of the required random sample size	64

A.1	Pearl string method: Number of specimens required for estimation of the mean number of cycles	64
A.2	Pearl string method: Number of specimens required for estimation of the slope k _{GG} of the S-N curve	70
Annex B (normative) Load level method: Determination of the required random sample size		76
B.1	Load level method: Required number of specimens from the entire test series for estimation of the mean number of cycles	76
B.2	Load level method: Number of specimens from the entire test series required for estimation of the slope of the S-N curve in the high cycle fatigue regime	82
Annex C (informative) Typical standard deviations in the high cycle fatigue regime		88
Annex D (informative) Examples of test protocols		89
D.1	Record sheet for a high cycle fatigue test series	90
D.2	Record sheet for a long life fatigue strength test series	91
Annex E (normative) Examples of test evaluations		92
E.1	Example: Evaluation of the S-N curve in the high cycle fatigue regime obtained using the pearl string method	92
E.1.1	Test results	92
E.1.2	Position and slope of the S-N curve in the high cycle fatigue regime	93
E.1.3	S-N curve in the high cycle fatigue regime for a failure probability of 50 %	94
E.1.4	Standard deviation of the test results	94
E.1.5	S-N curve in the high cycle fatigue regime for a failure probability of 10 %	96
E.1.6	S-N curve in the high cycle fatigue regime for a failure probability of 90 %	96
E.1.7	Graphical representation of the S-N curve in the high cycle fatigue regime	97
E.2	Example: Evaluation of the S-N curve in the high cycle fatigue regime obtained using the load level method	97
E.2.1	Test results	97
E.2.2	Mean and standard deviation for load level 1	98
E.2.3	Mean and standard deviation for load level 2	99
E.2.4	S-N curve in the high cycle fatigue regime for a failure probability of 50 %	100
E.2.5	S-N curve for a failure probability of 10 %	100
E.2.6	S-N curve in the high cycle fatigue regime for a failure probability of 90 %	101
E.2.7	Graphical representation the S-N curve in the high cycle fatigue regime	101
E.3	Example: Evaluation of the long life fatigue strength obtained using the staircase method	102
E.4	Example: Determination of the number of cycles at knee point and of the course of the S-N curves up to the ultimate number of cycles	104
E.4.1	Pearl string method	104
E.4.2	Load level method	105
E.5	Example: Graphical representation of the S-N curve	107
E.5.1	Pearl string method	107
E.5.2	Load level method	109
Bibliography		112