

# DIN EN ISO 4259-1:2018-04 (E)

## Petroleum and related products - Precision of measurement methods and results - Part 1: Determination of precision data in relation to methods of test (ISO 4259-1:2017)

---

<b>Contents</b>		<b>Page</b>
<b>European foreword</b>		<b>4</b>
<b>Foreword</b>		<b>5</b>
<b>Introduction</b>		<b>6</b>
<b>1</b>	<b>Scope</b>	<b>7</b>
<b>2</b>	<b>Normative references</b>	<b>7</b>
<b>3</b>	<b>Terms and definitions</b>	<b>7</b>
<b>4</b>	<b>Stages in the planning of an interlaboratory study for the determination of the precision of a test method</b>	<b>10</b>
4.1	General	10
4.2	Preparing a draft method of test	11
4.3	Planning a pilot study with at least two laboratories	11
4.4	Planning the ILS	11
4.5	Executing the ILS	12
<b>5</b>	<b>Statistical treatment of ILS results</b>	<b>13</b>
5.1	General recommendation	13
5.2	Pre-screen using GESD technique	13
5.3	Transformation of data and outlier tests	14
5.3.1	General	14
5.3.2	Outlier identification after pre-screening	17
5.3.3	Uniformity of repeatability	17
5.3.4	Uniformity of reproducibility	17
5.4	Rejection of complete data (from all laboratories) for a sample	17
5.5	Estimating missing or rejected values	18
5.5.1	One of the two repeat values missing or rejected	18
5.5.2	Both repeat values missing or rejected	18
5.6	Rejection test for outlying laboratories	18
5.7	Confirmation of selected transformation	19
5.7.1	General	19
5.7.2	Identification of excessively influential sample(s)	19
<b>6</b>	<b>Analysis of variance, calculation and expression of precision estimates</b>	<b>20</b>
6.1	General	20
6.2	Analysis of variance	20
6.2.1	Forming the sums of squares for the laboratories × samples interaction sum of squares	20
6.2.2	Forming the sum of squares for the exact analysis of variance	21
6.2.3	Degrees of freedom	21
6.2.4	Mean squares and analysis of variance	21
6.3	Expectation of mean squares and calculation of precision estimates	21
6.3.1	Expectation of mean squares with no estimated values	21
6.3.2	Expectation of mean squares with estimated values	22
6.3.3	Calculation of precision estimates	23
6.4	Expression of precision estimates of a method of test	24
6.5	Specification of scope for the test method	19

<b>7</b>	<b><i>R/r</i> ratio</b> .....	<b>26</b>
<b>Annex A</b>	<b>(normative) Determination of number of samples required</b> .....	<b>27</b>
<b>Annex B</b>	<b>(informative) Derivation of formula for estimating the number of laboratories and samples required to meet minimum 30 degrees of freedom</b> .....	<b>29</b>
<b>Annex C</b>	<b>(normative) Notation and tests</b> .....	<b>31</b>
<b>Annex D</b>	<b>(normative) Illustration of procedures using ILS results for Bromine Number and statistical tables</b> .....	<b>36</b>
<b>Annex E</b>	<b>(normative) Types of dependence and corresponding transformations</b> .....	<b>55</b>
<b>Annex F</b>	<b>(normative) Weighted linear regression analysis</b> .....	<b>61</b>
<b>Annex G</b>	<b>(normative) Rules for rounding</b> .....	<b>68</b>
<b>Annex H</b>	<b>(normative) GESD technique to simultaneously identify multiple outliers in a data set</b> ..	<b>70</b>
<b>Annex I</b>	<b>(informative) Glossary</b> .....	<b>78</b>
<b>Bibliography</b>	.....	<b>81</b>