

DIN EN ISO 10111:2019-04 (E)

Metallic and other inorganic coatings - Measurement of mass per unit area - Review of gravimetric and chemical analysis methods (ISO 10111:2019)

Contents		Page
European foreword		3
Foreword		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Principle	6
5	Special equipment	6
6	Preparation of test specimen	6
6.1	Size	6
6.2	Shape	6
6.3	Edge condition	6
6.4	Heat treatment	6
7	Measurement of coated area	7
7.1	Measurement method	7
7.2	Surface measuring equipment	7
7.2.1	Geometrical (projected) surface area	7
7.2.2	Surface area increase due to roughness (optional)	7
7.3	Number of measurements	7
8	Determination of mass of coating by chemical analysis	8
8.1	General	8
8.2	Restrictions	8
9	Gravimetric determination of mass of coating	8
9.1	Specimen size	8
9.2	Limitations	8
9.3	Restrictions	8
9.4	Gravimetric analysis equipment	8
9.5	Procedure	9
9.5.1	General	9
9.5.2	Difference method with dissolution of the coating	9
9.5.3	Direct weighing method with dissolution of the substrate	9
9.5.4	Difference method without dissolution	9
10	Calculations	10
10.1	Surface density	10
10.2	Thickness	10
Annex A (informative) Reagents for selective dissolution of metal layers		11
Bibliography		15