## ISO 17640:2018 (E)

Non-destructive testing of welds — Ultrasonic testing — Techniques, testing levels, and assessment

## **Contents**

	For	eword	
1	Sco	Scope	
2	Nor	Normative references	
3	Ter	Terms and definitions	
4	Syr	nbols	
5	Ger	General	
6	Information required prior to testing		
	6.1	Items to be specified	
	6.2	Specific information required before testing	
	6.3	Written test procedure	
7	Requirements for personnel and equipment		
	7.1	Personnel qualifications	
	7.2	Test equipment	
	7.3	Probe parameters	
	7.3.1	Test frequency	
	7.3.2	Angles of incidence	
	7.3.3	Transducer size	
	7.3.4	Adaptation of probes to curved scanning surfaces	
	7.3.5	Coupling media	
8	Tes	Testing volume	
9	Pre	Preparation of scanning surfaces	
10	Par	Parent metal testing	
11	Range and sensitivity setting		
	11.1	General	
	11.2	Reference for sensitivity setting	
	11.3	Evaluation levels	
	11.4	Transfer correction	
	11.5	Signal-to-noise ratio	
12	Tes	ting levels	
13	Tes	ting techniques	
	13.1	General	
	13.2	Manual scan path	
	13.3	Testing for imperfections perpendicular to the testing surface	
	13.4	Location of discontinuities	
	13.5	Evaluation of indications	
	13.5.1	General	
	13.5.2	Maximum echo amplitude	
	13.5.3	Discontinuity length	
	13.5.4	Discontinuity height	
	13.5.5	Characterization of discontinuities	

## 14 Test report

Annex A (normative) Testing levels for various types of welded joints

Page count: 30