

ISO 20903:2019 (E)

Surface chemical analysis — Auger electron spectroscopy and X-ray photoelectron spectroscopy — Methods used to determine peak intensities and information required when reporting results

Contents

| | |
|---------|--|
| | Foreword |
| | Introduction |
| 1 | Scope |
| 2 | Normative references |
| 3 | Terms and definitions |
| 4 | Symbols and abbreviated terms |
| 5 | Methods for peak-intensity determination — direct spectrum |
| 5.1 | General |
| 5.2 | Selection and subtraction of an inelastic background |
| 5.3 | Measurement of peak intensity |
| 5.3.1 | Measurement of peak height |
| 5.3.2 | Measurement of peak area |
| 5.4 | Measurement of a peak intensity with computer software |
| 5.5 | Measurement of peak intensities for a spectrum with overlapping peaks |
| 5.6 | Uncertainty in measurement of peak area |
| 6 | Methods for peak intensity determination — Auger-electron differential spectrum |
| 6.1 | General |
| 6.2 | Measurement of Auger-electron differential intensity |
| 6.3 | Uncertainties in measurement of Auger-electron differential intensity |
| 7 | Reporting of methods used to measure peak intensities |
| 7.1 | General requirements |
| 7.2 | Methods used to determine peak intensities in direct spectra |
| 7.2.1 | Intensity measurement for a single peak, as described in 5.2 and 5.3 |
| 7.2.2 | Intensity measurements from peak fitting, as described in 5.4 and 5.5 |
| 7.3 | Methods used to obtain and determine peak intensities in Auger-electron differential spectra |
| 7.3.1 | Method used to obtain differential spectra |
| 7.3.2 | Method used to determine peak intensities, as described in 6.2 |
| Annex A | (informative) Instrumental effects on measured intensities |
| Annex B | (informative) Useful integration limits for determination of peak intensities in XPS spectra |

Page count: 17