

# ISO 17700:2019-07 (E)

## Footwear - Test methods for upper components and insoles - Colour fastness to rubbing and bleeding

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Apparatus and materials .....</b>	<b>2</b>
4.1	Method A .....	2
4.2	Method B .....	3
4.3	Method C .....	4
4.4	Method D .....	5
<b>5</b>	<b>Sampling and conditioning .....</b>	<b>6</b>
5.1	Method A .....	6
5.2	Method B .....	7
5.3	Method C .....	7
5.4	Method D .....	7
<b>6</b>	<b>Test method .....</b>	<b>8</b>
6.1	Principle .....	8
6.1.1	Methods A and B .....	8
6.1.2	Method C .....	8
6.1.3	Method D .....	8
6.2	Procedure .....	9
6.2.1	Method A .....	9
6.2.2	Method B .....	10
6.2.3	Method C .....	12
6.2.4	Method D .....	12
<b>7</b>	<b>Test report .....</b>	<b>13</b>
7.1	Methods A and B .....	13
7.2	Method C .....	14
7.3	Method D .....	14
<b>Annex A (informative) Summary of test conditions normally used for method B .....</b>		<b>15</b>
<b>Bibliography .....</b>		<b>16</b>