

# ISO 21968:2019 (E)

## Non-magnetic metallic coatings on metallic and non-metallic basis materials — Measurement of coating thickness — Phase-sensitive eddy-current method

---

### Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Principle of measurement
5	Factors affecting measurement uncertainty
5.1	Basic influence of the coating thickness
5.2	Electrical properties of the coating
5.3	Geometry — Base material thickness
5.4	Geometry — Edge effects
5.5	Geometry — Surface curvature
5.6	Surface roughness
5.7	Lift-off effect
5.8	Probe pressure
5.9	Probe tilt
5.10	Temperature effects
5.11	Intermediate coatings
5.12	External electromagnetic fields
6	Calibration and adjustment of the instrument
6.1	General
6.2	Thickness reference standards
6.3	Methods of adjustment
7	Measurement procedure and evaluation
7.1	General
7.2	Number of measurements and evaluation
8	Uncertainty of the results
8.1	General remarks
8.2	Uncertainty of the calibration of the instrument
8.3	Stochastic errors
8.4	Uncertainties caused by factors summarized in Clause 5
8.5	Combined uncertainty, expanded uncertainty and final result
9	Precision
9.1	General
9.2	Repeatability (r)
9.3	Reproducibility limit (R)
10	Test report
Annex A	(informative) Eddy-current generation in a metallic conductor
A.1	General
A.2	Example 1 — Conductive coating on a non-conductive base material
A.3	Example 2 — Conductive coating on a conductive and/or magnetic base metal
A.4	Example 3 — Non-conductive coating on a conductive and/or magnetic base metal

**Annex B (informative) Basics of the determination of the uncertainty of a measurement of the used measurement method corresponding to ISO/IEC Guide 98-3**

- B.1 General**
- B.2 Type A**
- B.3 Type B**

**Annex C (informative) Basic performance requirements for coating thickness gauges based on the phase-sensitive eddy-current method described in this document**

- C.1 Technical specification**
- C.2 Check/verification of instruments and probes**
  - C.2.1 Prior to the supply, after repair and at regular intervals after use**
  - C.2.2 Performed on site**

**Annex D (informative) Examples for the experimental estimation of factors affecting the measurement accuracy**

- D.1 General**
- D.2 Edge effect**
- D.3 Base metal thickness**
- D.4 Surface curvature**
- D.5 Conductivity and permeability of the base metal**
- D.6 Lift-off-height**

**Annex E (informative) Table of the student factor**

**Annex F (informative) Example of uncertainty estimation**

- F.1 Sample details**
- F.2 Steps**

**Annex G (informative) Details on precision**

- G.1 General notes on the interlaboratory test**
- G.2 Samples**
- G.3 Thickness gauges**
- G.4 Calibration**
- G.5 Number of measurements**
- G.6 Evaluation**

**Page count: 39**