

# ISO 21398:2019-10 (E)

## Hard coal and coke - Guidance to the inspection of mechanical sampling systems

---

| <b>Contents</b>   |   | <b>Page</b> |
|---|---|-------------|
| Foreword .....  |   | iv          |
| Introduction .....  |   | v           |
| <b>1</b>  | <b>Scope .....</b>                              | <b>1</b>    |
| <b>2</b>  | <b>Normative references .....</b>               | <b>1</b>    |
| <b>3</b>  | <b>Terms and definitions .....</b>              | <b>1</b>    |
| <b>4</b>  | <b>Safety .....</b>                             | <b>1</b>    |
| <b>5</b>  | <b>General considerations .....</b>             | <b>2</b>    |
| <b>5.1</b>  | <b>Precision .....</b>                          | <b>2</b>    |
| <b>5.2</b>  | <b>Bias .....</b>                               | <b>2</b>    |
| <b>5.3</b>  | <b>Operation of sampling system .....</b>       | <b>2</b>    |
| <b>6</b>  | <b>Establishment of inspection system .....</b> | <b>2</b>    |
| <b>6.1</b>  | <b>General .....</b>                            | <b>2</b>    |
| <b>6.2</b>  | <b>Audit -- External .....</b>                  | <b>3</b>    |
| <b>6.3</b>  | <b>Audit -- Internal .....</b>                  | <b>3</b>    |
| <b>6.4</b>  | <b>Operational inspections .....</b>            | <b>3</b>    |
| <b>7</b>  | <b>Procedures .....</b>                         | <b>3</b>    |
| <b>7.1</b>  | <b>Audit -- External .....</b>                  | <b>3</b>    |
| <b>7.2</b>  | <b>Audit -- Internal .....</b>                  | <b>4</b>    |
| <b>7.3</b>  | <b>Operational inspections .....</b>            | <b>5</b>    |
| <b>8</b>  | <b>Quality control .....</b>                    | <b>6</b>    |
| <b>8.1</b>  | <b>General .....</b>                            | <b>6</b>    |
| <b>8.2</b>  | <b>Sampling ratio .....</b>                     | <b>6</b>    |
| <b>8.3</b>  | <b>Coefficient of variation .....</b>           | <b>6</b>    |
| <b>8.4</b>  | <b>Extraction ratio .....</b>                   | <b>7</b>    |
| <b>8.5</b>  | <b>Sampling records .....</b>                   | <b>7</b>    |
| <b>8.6</b>  | <b>Operators' inspection report .....</b>       | <b>7</b>    |
| <b>Annex A (informative) Monitoring coal sampling ratios using control charts .....</b>     |   | <b>11</b>   |
| <b>Annex B (informative) Examples of sampling checklists .....</b>                          |   | <b>15</b>   |
| <b>Annex C (informative) Example of sampling plant operator's inspection report .....</b>   |   | <b>18</b>   |
| <b>Annex D (informative) Examples of sampling plant operations inspection summary .....</b> |   | <b>21</b>   |
| <b>Bibliography .....</b>   |   | <b>23</b>   |