

# ISO 8222:2020-03 (E)

## Petroleum measurement systems - Calibration - Volumetric measures, proving tanks and field measures (including formulae for properties of liquids and materials)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions, symbols and units .....</b>	<b>1</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.2</b>	<b>Symbols and units .....</b>	<b>8</b>
<b>4</b>	<b>Traceability .....</b>	<b>9</b>
<b>5</b>	<b>General design characteristics of volumetric measures .....</b>	<b>10</b>
<b>5.1</b>	<b>General design .....</b>	<b>10</b>
<b>5.2</b>	<b>Design to indicate the volume -- Resolution .....</b>	<b>12</b>
<b>5.2.1</b>	<b>Neck size .....</b>	<b>12</b>
<b>5.2.2</b>	<b>Gauge glass .....</b>	<b>12</b>
<b>5.2.3</b>	<b>Scales .....</b>	<b>13</b>
<b>5.2.4</b>	<b>Adjustment of scale and calibrated volume .....</b>	<b>15</b>
<b>5.2.5</b>	<b>Levelling .....</b>	<b>15</b>
<b>5.3</b>	<b>Additional design aspects .....</b>	<b>15</b>
<b>5.3.1</b>	<b>Temperature measurement .....</b>	<b>15</b>
<b>5.3.2</b>	<b>Valves and connections .....</b>	<b>16</b>
<b>5.3.3</b>	<b>Size of measures .....</b>	<b>17</b>
<b>5.4</b>	<b>Filling and drainage .....</b>	<b>18</b>
<b>5.4.1</b>	<b>Drainage times and fluids .....</b>	<b>18</b>
<b>5.4.2</b>	<b>Filling and drainage methods .....</b>	<b>19</b>
<b>5.5</b>	<b>Markings .....</b>	<b>20</b>
<b>6</b>	<b>Test measures .....</b>	<b>21</b>
<b>6.1</b>	<b>Overview .....</b>	<b>21</b>
<b>6.2</b>	<b>Design and construction of test measures .....</b>	<b>23</b>
<b>7</b>	<b>Proving tanks .....</b>	<b>24</b>
<b>7.1</b>	<b>Overview .....</b>	<b>24</b>
<b>7.2</b>	<b>General construction .....</b>	<b>28</b>
<b>7.3</b>	<b>Bottom neck .....</b>	<b>28</b>
<b>7.4</b>	<b>Strength .....</b>	<b>29</b>
<b>7.5</b>	<b>Support .....</b>	<b>29</b>
<b>7.6</b>	<b>Size .....</b>	<b>29</b>
<b>7.7</b>	<b>Mobility .....</b>	<b>29</b>
<b>7.8</b>	<b>Overflow and vapour recovery .....</b>	<b>29</b>
<b>7.9</b>	<b>Filling and drainage .....</b>	<b>29</b>
<b>8</b>	<b>Alternative designs .....</b>	<b>30</b>
<b>8.1</b>	<b>High-accuracy designs .....</b>	<b>30</b>
<b>8.2</b>	<b>Automatic pipettes .....</b>	<b>30</b>
<b>8.3</b>	<b>Proving tanks with bottom sight gauge .....</b>	<b>30</b>

<b>9</b>	<b>Calibration</b> .....	<b>31</b>
<b>9.1</b>	<b>General</b> .....	<b>31</b>
<b>9.2</b>	<b>Common calibration procedures</b> .....	<b>31</b>
<b>9.3</b>	<b>Gravimetric calibration</b> .....	<b>33</b>
<b>9.3.1</b>	<b>Principle</b> .....	<b>33</b>
<b>9.3.2</b>	<b>Calibration circuit and equipment</b> .....	<b>33</b>
<b>9.3.3</b>	<b>Procedure for calibrating a measure gravimetrically</b> .....	<b>34</b>
<b>9.4</b>	<b>Volumetric calibration</b> .....	<b>34</b>
<b>9.4.1</b>	<b>Principle</b> .....	<b>34</b>
<b>9.4.2</b>	<b>Calibration circuit and equipment</b> .....	<b>35</b>
<b>9.4.3</b>	<b>Procedure for calibrating a measure volumetrically (water pour)</b> .....	<b>36</b>
<b>9.4.4</b>	<b>Procedure for calibrating a measure volumetrically (water withdraw)</b> .....	<b>36</b>
<b>9.4.5</b>	<b>Additional notes on procedures</b> .....	<b>37</b>
<b>9.5</b>	<b>Calibration by reference meter</b> .....	<b>38</b>
<b>9.5.1</b>	<b>Principle</b> .....	<b>38</b>
<b>9.5.2</b>	<b>Calibration circuit</b> .....	<b>38</b>
<b>9.5.3</b>	<b>Equipment</b> .....	<b>39</b>
<b>9.5.4</b>	<b>Procedure for calibration by reference meter</b> .....	<b>40</b>
<b>9.6</b>	<b>Calibration of neck scales</b> .....	<b>40</b>
<b>10</b>	<b>Calculations</b> .....	<b>41</b>
<b>10.1</b>	<b>Overview</b> .....	<b>41</b>
<b>10.2</b>	<b>Reference volume</b> .....	<b>41</b>
<b>10.3</b>	<b>Transferred volume (volumetric method)</b> .....	<b>42</b>
<b>10.4</b>	<b>Transferred volume (gravimetric method)</b> .....	<b>43</b>
<b>10.5</b>	<b>Calibrated volume of test device</b> .....	<b>44</b>
<b>10.6</b>	<b>Multiple fills</b> .....	<b>45</b>
<b>10.7</b>	<b>Calibration of a measure using a reference measure</b> .....	<b>45</b>
<b>10.8</b>	<b>Calibration of a flowmeter using a measure as reference</b> .....	<b>46</b>
<b>10.9</b>	<b>Calibration of a displacement (pipe) prover using a measure as reference</b> .....	<b>46</b>
<b>11</b>	<b>Calibrating and setting the neck and scale</b> .....	<b>46</b>
<b>11.1</b>	<b>Calibrating the neck</b> .....	<b>46</b>
<b>11.2</b>	<b>Setting the scales</b> .....	<b>47</b>
<b>12</b>	<b>Safety</b> .....	<b>48</b>
	<b>Annex A (informative) Properties of fluids and materials</b> .....	<b>49</b>
	<b>Annex B (informative) Temperature measurement and thermometers</b> .....	<b>63</b>
	<b>Annex C (informative) Standard glass contents measures</b> .....	<b>65</b>
	<b>Annex D (informative) Meniscus reading</b> .....	<b>66</b>
	<b>Annex E (informative) Accuracy and uncertainty of volumetric measures</b> .....	<b>67</b>
	<b>Bibliography</b> .....	<b>68</b>