

# ISO 23159:2020 (E)

## Non-destructive testing — Gamma ray scanning method on process columns

---

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Personnel qualification
5	Protection against ionizing radiation
6	Equipment requirements
7	Execution of work at site
7.1	Mechanical design of column and work permission
7.2	Execution of scanning
8	Data processing and reporting
8.1	Data processing and documentation
8.2	Report
Annex A	(informative) Recommendations for testing personnel
A.1	General
A.2	Level 3 (project manager)
A.3	Level 2 (senior field technician)
A.4	Level 1 (junior field technician)
Annex B	(informative) Selection of sealed radiation source and its activity
Annex C	(informative) Scanning equipment
Annex D	(informative) Preparation of the scanning equipment
D.1	Check list
D.1.1	General
D.1.2	Radiation source system
D.1.3	Radiation detection system
D.1.4	Scanning system
D.1.5	Radiological safety equipment
D.1.6	Others
D.2	Verification of the operational condition of the detection system
D.3	Field preparation
Annex E	(informative) Selection of sources — Detector orientations for scanning
E.1	Scanning of tray columns
E.2	Scanning of packed bed columns
Annex F	(informative) Interpretation of the scanning data
F.1	Models of reference profiles for a tray column
F.1.1	Scanning profile of a normally operating distillation column
F.1.2	Gamma scanning profile of a column part with foaming
F.1.3	Gamma profile of a column part with “weeping” (shower)

- F.1.4 Scanning profile through the downcomers**
- F.1.5 Scanning profile of flooding due to blockage at downcomer**
- F.1.6 Scanning profile of weeping condition**
- F.1.7 Damaged trays**
- F.2 Model of reference profiles for a packed bed column**

**Page count: 27**