

ISO 3452-2:2021 (E)

Non-destructive testing — Penetrant testing — Part 2: Testing of penetrant materials

Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Classification
4.1	Testing products
4.2	Sensitivity levels
4.2.1	General
4.2.2	Penetrant baseline sensitivity
4.2.3	Product family sensitivity
4.2.4	Fluorescent systems
4.2.5	Colour contrast systems
4.2.6	Dual-purpose product family
5	Testing of penetrant materials
5.1	Personnel
5.2	Testing facilities
5.2.1	Type testing
5.2.2	Batch testing
5.2.3	Process and control testing
5.3	Reporting
5.3.1	Type testing
5.3.2	Batch testing
5.4	Tests
5.4.1	Sensitivity test
5.4.2	Penetrants
5.4.3	Excess penetrant removers (excluding method A)
5.4.4	Developers
5.4.5	Batch tests for spray cans
6	Test methods and requirements
6.1	Appearance
6.2	Penetrant system sensitivity
6.2.1	Fluorescent penetrants (type I)
6.2.1.1	Qualification provisions
6.2.1.1.1	Penetrants (type I)
6.2.1.1.2	Developers
6.2.1.1.3	Solvent removers
6.2.1.2	Sensitivity
6.2.1.2.1	General
6.2.1.2.2	Test panels
6.2.1.2.3	Test procedures
6.2.1.2.4	Equipment
6.2.1.2.5	Interpretation of results
6.2.2	Colour contrast penetrants (type II)
6.2.2.1	Qualification provisions
6.2.2.2	Test panels
6.2.2.3	Method of testing
6.2.2.4	Interpretation of results

6.2.2.5	Requirements
6.3	Density
6.3.1	Test method
6.3.2	Requirements
6.4	Viscosity
6.4.1	Test method
6.4.2	Requirements
6.5	Flashpoint
6.5.1	Test method
6.5.2	Requirements
6.6	Washability (method A penetrants)
6.7	Fluorescent brightness
6.7.1	Test method
6.7.2	Requirements
6.8	UV stability
6.8.1	Test method
6.8.2	Requirements
6.9	Thermal stability of fluorescent brightness
6.9.1	Test method
6.9.2	Requirements
6.10	Water tolerance
6.10.1	Test method
6.10.2	Requirements
6.11	Corrosive properties
6.11.1	General
6.11.2	Type testing
6.11.2.1	Moderate temperature corrosion
6.11.2.1.1	Test procedure
6.11.2.1.2	Requirements
6.11.2.2	Compatibility with other materials
6.11.2.2.1	Test procedure
6.11.2.2.2	Requirements
6.11.2.3	High temperature titanium stress corrosion
6.11.2.3.1	Test panels
6.11.2.3.2	Specimen preparation
6.11.2.3.3	Test procedure
6.11.2.3.4	Interpretation
6.11.2.4	High-temperature corrosion of cast nickel alloys
6.11.2.4.1	Specimen preparation
6.11.2.4.2	Test procedure
6.11.2.4.3	Interpretation
6.11.3	Batch testing
6.11.3.1	Compatibility with metals
6.11.3.1.1	General
6.11.3.1.2	Requirements
6.11.3.2	Compatibility with other materials
6.11.3.2.1	General
6.11.3.2.2	Requirements
6.12	Content of sulfur and halogens (for products designated low in sulfur and halogens)
6.12.1	Test method
6.12.2	Requirements
6.13	Residue on evaporation/solid content
6.13.1	Solvent removers
6.13.1.1	Test procedure
6.13.1.2	Requirements
6.13.2	Form d and e developers
6.13.2.1	Test procedure
6.13.2.2	Requirements
6.14	Penetrant tolerance
6.14.1	Lipophilic emulsifier (method B)
6.14.2	Hydrophilic emulsifier (method D)
6.15	Developer performance
6.16	Re-dispersability
6.16.1	Water-suspendable developers

- 6.16.2 Solvent based developers (non-aqueous)
- 6.17 Density of carrier liquid
- 6.17.1 Test method
- 6.17.2 Requirements
- 6.18 Product performance (pressurized containers)
- 6.19 Particle size distribution
- 6.20 Water content
- 6.20.1 Test method
- 6.20.2 Requirements

7 Packaging and labelling

Annex A (normative) Comparison of fluorescent brightness

- A.1 Apparatus
- A.2 Preparation of filter paper specimens
- A.3 Measurement of fluorescent brightness
- A.4 Calculation

Annex B (normative) Equipment for determination of the visibility of fluorescent indications

- B.1 General configuration
- B.2 Image processing
- B.3 Evaluation

Annex C (informative) List of reference materials

Page count: 24