

# ISO 16190:2021-11 (E)

## Footwear - Critical substances potentially present in footwear and footwear components - Test method to quantitatively determine polycyclic aromatic hydrocarbons (PAHs) in footwear materials

---

<b>Contents</b>	<b>Page</b>
<b>Foreword</b> .....	<b>iv</b>
<b>Introduction</b> .....	<b>vi</b>
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms and definitions</b> .....	<b>1</b>
<b>4 Principle</b> .....	<b>1</b>
<b>5 Reagents</b> .....	<b>1</b>
<b>6 Apparatus</b> .....	<b>5</b>
<b>7 Sample preparation</b> .....	<b>5</b>
<b>8 Procedure</b> .....	<b>5</b>
8.1 Extraction.....	5
8.2 Optional: Solid-phase extraction (SPE) clean-up.....	6
8.3 Determination by GC-MS or GC-MS/MS.....	6
<b>9 Expression of results</b> .....	<b>6</b>
9.1 Determination of the PAH content.....	6
9.1.1 For each PAH.....	6
9.1.2 When a sum of PAHs is requested.....	6
9.2 Performance of the test method.....	7
<b>10 Test report</b> .....	<b>7</b>
<b>Annex A (informative) Examples of chromatographic conditions for GC-MS and GC-MS/MS</b> .....	<b>8</b>
<b>Bibliography</b> .....	<b>11</b>