

ISO 10111:2000-06 (E)

Metallic and other inorganic coatings - Measurement of mass per unit area - Review of gravimetric and chemical analysis methods

Contents		Page
Foreword	iv
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
4	Principle	3
5	Special equipment	3
6	Preparation of test specimen	3
7	Measurement of coated area	4
8	Determination of mass of coating by chemical analysis	4
9	Gravimetric determination of mass of coating	5
10	Calculations	6
Annex A (normative) Reagents for selective dissolution of metal layers		7
Bibliography		13