

ISO 24543:2022-09 (E)

Non-destructive testing - Acoustic emission testing - Verification of the receiving sensitivity spectra of piezoelectric acoustic emission sensors

Contents		Page
	Foreword.....	v
	Introduction.....	vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	3
5	Overview	4
5.1	Face-to-face setup — Block diagram.....	4
5.2	Laser vibrometer setup — Block diagram.....	5
6	General requirements related to hardware	6
6.1	General.....	6
6.2	Requirements related to the function generator (FG).....	6
6.3	Requirements related to the transmitter.....	7
6.4	Requirements related to the coupling agent between transmitter and sensor under test.....	8
6.5	Requirements related to the sensor-to-transmitter fixing tool.....	8
6.5.1	General.....	8
6.5.2	Requirements.....	8
6.6	Requirements related to the sensor under test (SUT).....	9
6.6.1	General.....	9
6.6.2	Pyroelectric effect.....	9
6.6.3	Integrated pre-amplifier.....	10
6.6.4	Influence of the pre-amplifier input impedance.....	10
6.6.5	Requirements for a list of sensors under test.....	10
6.7	Requirements related to the signal cable from sensor to transient recorder.....	10
6.7.1	General.....	10
6.7.2	Requirement.....	10
6.8	Requirements related to the signal cable from the function generator to the transmitter and to the transient recorder.....	10
6.9	Requirements related to the transient recorder for measuring U_S and U_F	11
6.9.1	General.....	11
6.9.2	Input impedance.....	11
6.9.3	Range, resolution, accuracy, sampling rate and buffer length.....	11
6.9.4	Bandwidth.....	12
6.9.5	Trigger settings.....	12
6.9.6	Verification — Calibration.....	12
7	Determination of the receiving sensitivity spectra	12
7.1	General.....	12
7.2	Formulae for the determination of receiving sensitivity spectra R_D and R_V	12
7.3	Relevant spectra for sensor sensitivity verification.....	13
7.4	Procedure for sensor sensitivity verification.....	14
7.4.1	Preparation.....	14
7.4.2	Cable connections for the face-to-face setup.....	15
7.4.3	Settings of the function generator in the face-to-face setup.....	15
7.4.4	Setting of the transient recorder.....	16
7.4.5	Trial measurement.....	17
7.4.6	Initial crosstalk test.....	18

7.4.7	Capturing data of the sensor under test — Stimulation pulse U_F , sensor response U_S	18
7.4.8	Calculating and presenting receiving sensitivity spectra.....	19
7.4.9	Sensor verification report.....	20
7.5	Reproducibility of sensitivity spectra.....	21
7.5.1	Sensor-to-transmitter coupling.....	21
7.5.2	Influence of temperature.....	21
7.5.3	Change of the transmitter.....	21
8	Determination of the transmitting sensitivity spectra.....	22
8.1	Formula for the determination of the transmitting displacement sensitivity.....	22
8.2	Requirements related to the scanning laser vibrometer.....	23
8.3	Procedure for the determination of transmitting sensitivities T_D	24
8.3.1	Preparation.....	24
8.3.2	Cable connections for the laser vibrometer setup.....	24
8.3.3	Function generator settings for the laser vibrometer setup.....	24
8.3.4	Capturing laser vibrometer data.....	25
8.3.5	Calculating the displacement results.....	25
8.4	After completion of the motion measurement.....	26
8.5	Criteria to sort out unsuitable transmitters.....	26
8.6	Calibration of the laser vibrometer.....	28
8.7	Detection of a drift of a transmitting sensitivity.....	28
	Annex A (informative) Examples of templates.....	30
	Annex B (informative) Examples of equipment.....	32
	Annex C (informative) Verification methods for piezoelectric acoustic emission sensors.....	34
	Annex D (informative) Additional information concerning receiving sensitivity determination.....	38
	Annex E (informative) Additional information concerning transmitting sensitivity determination.....	51
	Annex F (informative) Adapting R_V/R_D to the acoustic impedances of the used materials.....	58
	Bibliography.....	60