

ISO 5722:2023-03 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) - Test method for determining tensile and shear creep of ceramic adhesive

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Apparatus	2
6	Test specimen	3
6.1	Test specimen size and preparation	3
6.2	Test specimen storage	6
7	Test procedures	6
7.1	Measurement of specimen dimensions	6
7.2	Measurements of the tensile or shear creep	6
7.3	Measurements of the cross-bonded area and thickness	9
7.4	Loading procedure	9
7.5	Recording of displacement and rupture time	9
8	Calculation of results	9
8.1	Calculation of the tensile creep	9
8.2	Calculation of the shear creep	9
9	Test report	10
Bibliography		11