

ISO 4917-6:2024-02 (E)

Design of nuclear power plants against seismic events - Part 6: Post-seismic measures

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Procedure	2
4.1	General requirements	2
4.2	Verification of the earthquake	2
4.3	Classification of the earthquake	3
4.4	Initial measures	3
4.4.1	Plant check-up from the control room and plant walk-down inspection (Figure 2, chart item 3)	3
4.4.2	Deviations caused by the earthquake (Figure 2, chart item 4)	4
4.4.3	Specified normal operation condition in accordance with the operating manual (Figure 2, chart item 5)	4
4.5	In-depth measures	4
4.5.1	General	4
4.5.2	Special/Seismic inspections and analyses (Figure 2, chart item 6)	4
4.5.3	Specified normal operation condition and permissible loads (Figure 2, chart item 7)	5
4.5.4	Shutdown inspection (Figure 2, chart item 9)	5
4.6	Resulting measures	5
4.6.1	Continued operation (Figure 2, chart item 8)	5
4.6.2	Shutting down the plant (Figure 2, chart item 10)	5
4.6.3	Additional procedures (Figure 2, chart item 11)	6
	Annex A (informative) Derivation of factor, f	7
	Annex B (informative) Directives for plant walk-down inspections	9
	Annex C (informative) Special/Seismic inspections	10
	Bibliography	12