

# ISO 4917-6:2024-02 (E)

## Design of nuclear power plants against seismic events - Part 6: Post-seismic measures

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Procedure .....	2
4.1	General requirements .....	2
4.2	Verification of the earthquake .....	2
4.3	Classification of the earthquake .....	3
4.4	Initial measures .....	3
4.4.1	Plant check-up from the control room and plant walk-down inspection (Figure 2, chart item 3) .....	3
4.4.2	Deviations caused by the earthquake (Figure 2, chart item 4) .....	4
4.4.3	Specified normal operation condition in accordance with the operating manual (Figure 2, chart item 5) .....	4
4.5	In-depth measures .....	4
4.5.1	General .....	4
4.5.2	Special/Seismic inspections and analyses (Figure 2, chart item 6) .....	4
4.5.3	Specified normal operation condition and permissible loads (Figure 2, chart item 7) .....	5
4.5.4	Shutdown inspection (Figure 2, chart item 9) .....	5
4.6	Resulting measures .....	5
4.6.1	Continued operation (Figure 2, chart item 8) .....	5
4.6.2	Shutting down the plant (Figure 2, chart item 10) .....	5
4.6.3	Additional procedures (Figure 2, chart item 11) .....	6
	Annex A (informative) Derivation of factor, f .....	7
	Annex B (informative) Directives for plant walk-down inspections .....	9
	Annex C (informative) Special/Seismic inspections .....	10
	Bibliography .....	12