

# DIN EN ISO 7539-6:2024-09 (E)

Corrosion of metals and alloys - Stress corrosion testing - Part 6: Preparation and use of precracked specimens for tests under constant load or constant displacement (ISO 7539-6:2018, Corrected version 2018-11 + Amd 1:2024) (includes Amendment A1:2024)

---

<b>Contents</b>		<b>Page</b>
European foreword.....		3
▣ European foreword to Amendment 1 ▣.....		4
Foreword.....		5
▣ Foreword to Amendment 1 ▣.....		6
<b>1</b> Scope.....		<b>7</b>
<b>2</b> Normative references.....		<b>7</b>
<b>3</b> Terms and definitions.....		<b>7</b>
<b>4</b> Principle.....		<b>10</b>
<b>5</b> Specimens.....		<b>10</b>
5.1 General.....		10
5.2 Specimen design.....		12
5.3 Stress intensity factor considerations.....		23
5.4 Specimen preparation.....		29
5.5 Specimen identification.....		31
<b>6</b> Initiation and propagation of fatigue cracks.....		<b>31</b>
<b>7</b> Procedure.....		<b>33</b>
7.1 General.....		33
7.2 Environmental considerations.....		33
7.3 Environmental chamber.....		33
7.4 Environmental control and monitoring.....		34
7.5 Determination of $K_{ISCC}$ by crack arrest.....		35
7.6 Determination of $K_{ISCC}$ by crack initiation.....		38
7.7 Measurement of crack velocity.....		40
<b>8</b> Test report.....		<b>40</b>
<b>Annex A (informative) Use of notched specimens for stress corrosion tests.....</b>		<b>42</b>
A.1 General.....		42
A.2 Symbols.....		42
A.3 Principle.....		42
A.4 Specimens.....		43
A.4.1 General.....		43
A.4.2 Specimen design.....		43
A.4.3 Stress considerations.....		43
A.4.4 Specimen preparation.....		44
A.5 Procedure.....		44
A.6 Test report.....		44
<b>Annex B (informative) Determination of crack growth velocity.....</b>		<b>45</b>
<b>Bibliography.....</b>		<b>46</b>