

DIN CEN/TS 18094:2025-02 (E)

Non-destructive testing - Test method for determining residual stresses by synchrotron x-ray diffraction; English version CEN/TS 18094:2024

Contents		Page
European foreword		4
Introduction		5
1 Scope.....		6
2 Normative references.....		6
3 Terms and definitions		6
4 Symbols and abbreviated terms.....		11
4.1 Symbols and units.....		11
4.2 Subscripts		12
4.3 Abbreviations.....		12
5 Summary of the synchrotron XRD measurement method.....		12
5.1 General.....		12
5.2 Diffraction techniques.....		14
5.2.1 General information		14
5.2.2 Effects due to the material structure		15
5.3 Synchrotron high energy X-ray diffraction.....		16
5.3.1 General.....		16
5.3.2 Monochromatic beam for angle-dispersive X-ray diffraction (ADXRD)		16
5.3.3 Polychromatic beam for energy-dispersive X-ray diffraction (EDXRD)		17
5.4 Residual stress calculation.....		17
5.4.1 Strain		17
5.4.2 Stress		19
5.5 Sources of error and uncertainty		21
5.5.1 Errors and misapplications.....		21
5.5.2 Uncertainties		22
6 Preparation of measurement and calibration.....		23
6.1 Sample preparation		23
6.1.1 General.....		23
6.1.2 Geometry.....		23
6.1.3 Composition.....		23
6.1.4 Thermal/mechanical history.....		24
6.1.5 Phases and crystals		24
6.1.6 Homogeneity, microstructure and texture.....		24
6.1.7 Grain size		24
6.2 Instrumentation preparation.....		24
6.2.1 Instrumentation calibration		24
6.2.2 Verification of the instrumentation		24
6.3 Experimental setup		25
6.3.1 Choosing the measurement method and beam type.....		25
6.3.2 Reflection geometry.....		25
6.3.3 Transmission geometry.....		25
6.3.4 Energy-dispersive (EDXRD) mode.....		25
6.3.5 Angle dispersive (ADXRD) mode.....		25
6.3.6 Determination of the gauge volume (GV).....		26
6.3.7 Peak selection		26

6.3.8	Temperature	27
6.4	Measurement procedure: EDXRD – transmission.....	27
6.4.1	General considerations	27
6.4.2	Calibration of the detector	27
6.4.3	Instrument alignment.....	27
6.4.4	Calibration of scattering angle.....	27
6.5	Measurement procedure: EDXRD – reflection	28
6.5.1	General considerations	28
6.5.2	Calibration of detector.....	28
6.5.3	Instrument alignment.....	28
6.5.4	Calibration of scattering angle.....	28
6.5.5	Determination of gauge volume (GV).....	28
6.5.6	Sample positioning.....	29
6.5.7	Slit positioning.....	29
6.6	Measurement procedure: ADXRD – transmission and reflection	29
6.6.1	General considerations	29
6.6.2	Calibration of detector.....	29
6.6.3	Instrument alignment.....	30
6.6.4	Calibration of scattering angle.....	30
6.6.5	Detector distance.....	30
6.6.6	Defining beam parameters.....	30
6.6.7	Performing the measurement.....	31
6.7	Measurement procedure: ADXRD – CSC	31
6.7.1	General considerations	31
6.7.2	Calibration of detector.....	31
6.7.3	Instrument alignment.....	31
7	Measurement and recording requirements	31
7.1	General	31
7.2	Measurements	31
7.3	Recording requirements.....	32
7.4	Reduction of measurement data and data fitting	32
8	Data analysis and stress calculation.....	33
8.1	Specific equations for synchrotron radiation-based diffraction techniques.....	33
8.1.1	General	33
8.1.2	Data input.....	33
8.1.3	Stress-free reference input.....	34
8.1.4	Strain calculation.....	34
8.1.5	Elastic constant input.....	34
8.1.6	Stress calculation.....	34
8.2	Evaluation of uncertainty in the measurement.....	35
8.2.1	Random and systematic uncertainties	35
8.2.2	Interlaboratory comparison.....	36
8.3	Description of the final residual stress data output format.....	36
9	Reporting.....	37
Annex A (informative)	Reference samples.....	38
Annex B (informative)	Harmonization of data structures.....	41
Bibliography	47