

# ISO 1953:2025-10 (E)

## Coal - Size analysis by sieving

---

<b>Contents</b>		<b>Page</b>
Foreword.....		iv
Introduction.....		v
<b>1</b> <b>Scope</b> .....		<b>1</b>
<b>2</b> <b>Normative references</b> .....		<b>1</b>
<b>3</b> <b>Terms and Definitions</b> .....		<b>1</b>
<b>4</b> <b>Apparatus</b> .....		<b>1</b>
4.1    For all methods.....		2
4.2    For dry sieving.....		2
4.3    For wet sieving.....		2
<b>5</b> <b>Sampling and preparation</b> .....		<b>3</b>
5.1    Sampling.....		3
5.2    Preparation.....		3
5.3    Division of the gross sample, other than wet coal of less than 4 mm.....		4
5.4    Division of the gross sample of wet coal less than 4 mm.....		4
5.5    Drying of test sample for sizing.....		4
5.6    Equilibration of test samples dried at enhanced temperature.....		4
5.7    Equilibration periods.....		4
<b>6</b> <b>Procedure</b> .....		<b>4</b>
6.1    General.....		4
6.2    Dry sieving.....		5
6.2.1    Test sample of maximum particle size greater than 22,4 mm.....		5
6.2.2    Sample of maximum particle size between 4 mm and 22,4 mm — Manual method.....		5
6.2.3    Sample of maximum particle size less than 4 mm — Manual method.....		6
6.2.4    Sample of maximum particle size between 4 mm and 22,4 mm; minus 4 mm — Mechanical method.....		7
6.3    Wet sieving.....		7
<b>7</b> <b>Expression of results</b> .....		<b>8</b>
7.1    Calculation.....		8
7.2    Graphical presentation.....		8
<b>8</b> <b>Test report</b> .....		<b>8</b>
<b>Annex A</b> (informative) <b>Guide to sampling</b> .....		<b>13</b>
<b>Annex B</b> (informative) <b>Example of removal by wet sieving of fine material from a sample having a maximum particle size less than 4 mm</b> .....		<b>14</b>
<b>Annex C</b> (informative).....		<b>15</b>