

# DIN EN ISO 2719:2026-03 (E)

## Determination of flash point - Pensky-Martens closed cup method (ISO 2719:2025)

---

### Contents

	Page
Foreword.....	iv
Introduction.....	v
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative references</b> .....	<b>1</b>
<b>3 Terms and definitions</b> .....	<b>1</b>
<b>4 Principle</b> .....	<b>2</b>
<b>5 Chemicals and materials</b> .....	<b>2</b>
<b>6 Apparatus</b> .....	<b>2</b>
<b>7 Apparatus preparation</b> .....	<b>3</b>
7.1 General.....	3
7.2 Location of the apparatus.....	3
7.3 Cleaning the test cup.....	3
7.4 Apparatus assembly.....	3
7.5 Apparatus verification.....	3
<b>8 Sampling</b> .....	<b>4</b>
<b>9 Sample handling</b> .....	<b>5</b>
9.1 Petroleum products.....	5
9.1.1 Sub-sampling.....	5
9.1.2 Samples containing undissolved water.....	5
9.1.3 Samples that are liquid at ambient temperature.....	5
9.1.4 Samples that are very viscous, semi-solid or solid at ambient temperature.....	5
9.2 Paints and varnishes.....	5
<b>10 Procedure</b> .....	<b>6</b>
10.1 General.....	6
10.2 Procedure A.....	6
10.3 Procedure B.....	7
10.4 Procedure C.....	8
<b>11 Calculation</b> .....	<b>9</b>
11.1 Conversion of barometric pressure reading.....	9
11.2 Correction of detected flash point.....	9
<b>12 Expression of results</b> .....	<b>9</b>
<b>13 Precision</b> .....	<b>9</b>
13.1 General.....	9
13.2 Repeatability, <i>r</i> .....	9
13.3 Reproducibility, <i>R</i> .....	10
<b>14 Test report</b> .....	<b>11</b>
<b>Annex A (normative) Apparatus verification using reference materials</b> .....	<b>12</b>
<b>Annex B (normative) Pensky-Martens closed cup test apparatus</b> .....	<b>15</b>
<b>Annex C (normative) Temperature measuring device specification</b> .....	<b>23</b>
<b>Annex D (normative) Requirements for hot wire ignitors and flash point detectors</b> .....	<b>25</b>
<b>Bibliography</b> .....	<b>27</b>