

ISO 25086-1:2026-01 (E)

Textiles - Determination of the snagging resistance of fabrics - Part 1: Mace (spiked ball) test method

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	1
5 Apparatus	2
6 Pre-treatment of fabric	4
7 Atmosphere for conditioning and testing	4
8 Preparation of test specimens	4
9 Procedure	5
9.1 Mounting of the felt.....	5
9.2 Checking and adjustment of the mace (spiked ball).....	5
9.3 Setting of the testing time.....	6
9.4 Test specimen mounting.....	6
9.5 Testing running.....	6
10 Assessment of snagging	6
11 Test report	7
Bibliography	9