

# ISO 3497:2000-12 (E)

## Metallic coatings - Measurement of coating thickness - X-ray spectrometric methods

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	<b>Scope .....</b>	<b>1</b>
2	<b>Terms and definitions .....</b>	<b>1</b>
3	<b>Principle .....</b>	<b>3</b>
4	<b>Apparatus .....</b>	<b>7</b>
5	<b>Factors that influence the measurement results .....</b>	<b>10</b>
6	<b>Calibration of instrument .....</b>	<b>14</b>
7	<b>Procedure .....</b>	<b>16</b>
8	<b>Measurement uncertainty .....</b>	<b>17</b>
9	<b>Test report .....</b>	<b>17</b>
<b>Annex A (informative) Typical measuring ranges for some common coating materials .....</b>		<b>18</b>