

# ISO 6570:2001-06 (E)

## Natural gas - Determination of potential hydrocarbon liquid content - Gravimetric methods

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Principle .....	2
4	Apparatus requirements .....	2
4.1	Measurement installation .....	2
4.2	Check for correct installation operation .....	5
5	Sampling .....	10
5.1	General .....	10
5.2	Sampling conditions .....	10
5.3	Sample line .....	10
5.4	Direct sampling .....	10
5.5	Indirect sampling .....	10
6	Procedure .....	11
6.1	Determination of potential hydrocarbon liquid content .....	11
6.2	Determination of water formation .....	12
7	Expression of results .....	12
7.1	Method A -- Manual weighing method .....	12
7.2	Method B -- Indirect automatic method .....	14
8	Uncertainty of measurement .....	15
8.1	Achievable uncertainty .....	15
8.2	Gas leakage .....	15
8.3	Bath liquid .....	16
8.4	Wet gas .....	16
8.5	Condensate leakage .....	16
8.6	Variations in bath temperature and pressure in the gas/liquid cyclone separator .....	16
8.7	Premature condensation .....	16
9	Test report .....	16
Annex A (informative) Selection of measurement temperature and pressure .....		17
Annex B (informative) Examples of the line-up of the apparatus .....		18
Annex C (informative) Example of calibration of the differential pressure gauge for the indirect automatic method -- Method B .....		19
Annex D (informative) Example of an indirect automatic measurement -- Method B .....		21