

ISO 13909-3:2001-12 (E)

Hard coal and coke - Mechanical sampling - Part 3: Coal; Sampling from stationary lots

Contents		Page
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Establishing a sampling scheme	2
5	Methods of sampling from wagons, barges and ships	9
6	Methods of sampling from stockpiles	11
7	Sampling equipment -- mechanical auger	12
8	Handling and storage of samples	13
9	Sample preparation	14
10	Minimization of bias	14
11	Verification	15
Annex A Examples of calculations of the number of sub-lots and number of increments per sub-lot (sampling from stationary lots)		16
Bibliography		19