

# ISO 13909-5:2001-12 (E)

## Hard coal and coke - Mechanical sampling - Part 5: Coke; Sampling from moving streams

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Establishing a sampling scheme .....</b>	<b>1</b>
<b>5</b>	<b>Methods of sampling .....</b>	<b>8</b>
<b>6</b>	<b>Design of mechanical samplers .....</b>	<b>11</b>
<b>7</b>	<b>Handling and storage of samples .....</b>	<b>19</b>
<b>8</b>	<b>Sample preparation .....</b>	<b>20</b>
<b>9</b>	<b>Minimization of bias .....</b>	<b>20</b>
<b>10</b>	<b>Verification .....</b>	<b>21</b>
<b>Annexes A</b>	<b>Examples of calculations of the number of sub-lots and number of increments per sub-lot for moving streams of coke .....</b>	<b>22</b>
<b>B</b>	<b>Evaluation of sampling equipment for mass-basis sampling .....</b>	<b>24</b>
<b>C</b>	<b>Guidance on the operation of mechanical samplers .....</b>	<b>28</b>
	<b>Bibliography .....</b>	<b>29</b>