

ISO 21687:2007-03 (E)

Carbonaceous materials used in the production of aluminium - Determination of density by gas pycnometry (volumetric) using helium as the analysis gas - Solid materials

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		1
3 Terms and definitions		1
4 Principle		2
5 Apparatus and materials		2
6 Sampling, sample preparation and drying		2
7 Procedure		3
8 Calculation		3
9 Precision		4
10 Test report		5
Bibliography		6