

# DIN EN ISO 5398-4:2007-10 (E)

Leather - Chemical determination of chromic oxide content - Part 4: Quantification by inductively coupled plasma - optical emission spectrometer (ICP-OES) (ISO 5398-4:2007)

---

| <b>Contents</b>  | <b>Page</b> |
|--|-------------|
| Foreword.....  | 3           |
| Introduction .....   | 4           |
| 1 Scope .....  | 5           |
| 2 Normative references .....   | 5           |
| 3 Terms and definitions .....  | 5           |
| 4 Principle.....   | 6           |
| 5 Sampling and sample preparation .....                                      | 6           |
| 6 Reagents.....  | 6           |
| 6.1 Wet oxidation method .....   | 6           |
| 6.2 ICP-OES .....  | 6           |
| 7 Apparatus .....  | 6           |
| 8 Methods .....  | 7           |
| 8.1 Preparation of analytical solution.....                                  | 7           |
| 8.2 Measurement of the aqueous solution.....                                 | 7           |
| 9 Calculation and expression of results.....                                 | 8           |
| 10 Test report .....   | 9           |
| Annex A (informative) Determination of water and other volatile matter ..... | 10          |