

# ISO 13503-3:2022-04 (E)

## Petroleum and natural gas industries - Completion fluids and materials - Part 3: Testing of heavy brines

---

Contents	Page
<b>Foreword .....</b>	<b>iv</b>
<b>Introduction .....</b>	<b>vi</b>
<b>1 Scope .....</b>	<b>1</b>
<b>2 Normative references .....</b>	<b>1</b>
<b>3 Terms and definitions .....</b>	<b>1</b>
<b>4 Supplements to API RP 13J, 5th edition (2014) .....</b>	<b>2</b>
<b>4.1 General .....</b>	<b>2</b>
<b>4.2 Method for determining iron content .....</b>	<b>2</b>
<b>4.3 Method for determining carbonate and bicarbonate concentrations .....</b>	<b>2</b>
<b>4.3.1 General .....</b>	<b>2</b>
<b>4.3.2 Determination of carbonate concentration by titration in the titration sample .....</b>	<b>2</b>
<b>4.3.3 Calculation of carbonate fraction in the titration sample .....</b>	<b>3</b>
<b>4.3.4 Calculation of bicarbonate concentration in the titration sample .....</b>	<b>5</b>
<b>4.3.5 Calculation of total carbonate and bicarbonate concentration .....</b>	<b>5</b>
<b>4.3.6 Calculation of carbonate and bicarbonate concentrations in the original sample (before pH adjustment) .....</b>	<b>5</b>
<b>4.4 Method for determining CT .....</b>	<b>6</b>
<b>4.4.1 General .....</b>	<b>6</b>
<b>4.4.2 Application and procedure .....</b>	<b>7</b>
<b>4.4.3 Preparation of seeding material .....</b>	<b>7</b>
<b>4.4.4 Selection of seeding material .....</b>	<b>8</b>
<b>4.4.5 Determination of approximate CT .....</b>	<b>11</b>
<b>4.4.6 Accurate determination of CT .....</b>	<b>11</b>
<b>4.5 Method for measuring pH of formate brines .....</b>	<b>14</b>