

ISO 20815:2026-06 (E)

Oil and gas industries including lower carbon energy - Production assurance and reliability management

Contents

Page

Foreword.....	iv
Introduction	v
1 Scope	1
2 Normative references	2
3 Terms, definitions and abbreviated terms	2
3.1 Terms and definitions	2
3.2 Abbreviated terms	22
4 Production assurance and decision support	23
4.1 Framework conditions	23
4.1.1 General	23
4.1.2 Sustainability and climate change considerations	25
4.2 Optimization process	26
4.3 Production assurance programme	27
4.3.1 Objectives	27
4.3.2 Project risk categorization	28
4.3.3 Programme activities	29
4.4 Alternative standards	31
5 Production assurance processes and activities	32
Annex A (normative) Production assurance programme (PAP) and reliability management programme (RMP) — Structure and content	34
Annex B (informative) Core production assurance processes and activities	36
Annex C (informative) Interacting production assurance processes and activities	47
Annex D (informative) Production performance analyses	52
Annex E (normative) Reliability and production performance data	58
Annex F (informative) Performance objectives and requirements	61
Annex G (normative) Performance measures for production assurance	65
Annex H (informative) Relationship to major accidents	72
Annex I (informative) Outline of techniques	74
Bibliography	101