

ISO 13506-1:2017-07 (E)

Protective clothing against heat and flame - Part 1: Test method for complete garments - Measurement of transferred energy using an instrumented manikin

Contents	Page
Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	2
3 Terms and definitions	2
4 General	4
5 Apparatus	5
6 Sampling and test specimens	18
6.1 General	18
6.2 Number of test specimens	19
6.3 Size of test specimen	19
6.4 Specimen preparation	19
6.4.1 Conditioning	19
6.4.2 Optional laundering	19
6.5 Standard reference garment design	19
7 Pre-requisites for products implementing this test method	20
8 Procedure	21
8.1 Preparation of test apparatus	21
8.1.1 General	21
8.1.2 Manikin sensor check	21
8.1.3 Flame exposure chamber purging	22
8.1.4 Gas line charging	22
8.1.5 Confirmation of nude exposure conditions	22
8.2 Specimen testing procedure	23
8.2.1 General	23
8.2.2 Dressing the manikin	23
8.2.3 Recording the specimen identification, test conditions and test observations	23
8.2.4 Confirming safe operation conditions and lighting of pilot flames	24
8.2.5 Starting the image recording system	24
8.2.6 Setting time for heat transfer data acquisition	24
8.2.7 Exposure of the test specimen	25
8.2.8 Recording of specimen response remarks	25
8.2.9 Calculation of surface incident heat flux and transferred energy	25
8.2.10 Still images	25
8.3 Preparing for the next test exposure	25
9 Test report	26
9.1 General	26
9.2 Specimen identification	26
9.3 Exposure conditions	26
9.4 Results for each specimen	27
9.4.1 General	27

9.4.2	Heat flux data of each manikin sensor	27
9.4.3	Transferred energy	27
9.4.4	Energy transmission factor	27
9.4.5	Other information that may be reported	28
9.5	Observations	28
Annex A (informative) Considerations for conducting tests and using test results		29
Annex B (informative) Inter-laboratory test data analysis		30
Annex C (normative) Calibration procedure		33
Annex D (informative) Calculation of transferred energy and energy transmission factor		42
Annex E (informative) Elements of a computer software program		45
Bibliography		47