

ISO 17492:2019-10 (E)

Clothing for protection against heat and flame - Determination of heat transmission on exposure to both flame and radiant heat

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	3
5	Apparatus	4
6	Precautions	8
7	Sampling	9
7.1	Specimen dimensions	9
7.2	Number of specimens	9
8	Conditioning and testing atmospheres	9
8.1	Conditioning atmosphere	9
8.2	Testing atmosphere	9
9	Test procedure	9
9.1	Initial set up and calibration procedures	9
9.1.1	Initial set up of the system and alignment of burner flames	9
9.1.2	Initial setting of the 50/50 mix of convective and radiant heat	9
9.1.3	Setting the radiant heat from the lamps	9
9.1.4	Setting the total exposure heat flux	10
9.2	Sensor care	10
9.2.1	Sensor care	10
9.2.2	Sensor inspection	10
9.2.3	Surface reconditioning	10
9.3	Specimen holder care	11
9.4	Computer processing of data	11
9.5	Test specimen mounting	12
9.5.1	Single layer specimens	12
9.5.2	Multilayer assembly specimens	12
9.6	Test specimen exposure when both TPI and HTI(DE) are measured	12
9.7	Test specimen exposure when only HTI(DE) is measured	13
10	Expression of results	13
10.1	Selection of analysis method	13
10.2	Thermal protection index analysis method	13
10.2.1	Time to onset of burn injury	13
10.2.2	Thermal protection index	13
10.3	HTI(DE) analysis method	14
10.4	Response to convective and radiant heat exposure	14
11	Interlaboratory test data	14

12	Test report	14
	Annex A (informative) Availability of materials	15
	Annex B (informative) Basis of sensor calibration	17
	Annex C (informative) Interlaboratory test data	18
	Bibliography	19