

DIN EN ISO 13506-1:2024-12 (E)

Protective clothing against heat and flame - Part 1: Test method for complete garments - Measurement of transferred energy using an instrumented manikin (ISO 13506-1:2024)

Contents

	Page
European foreword.....	4
Foreword.....	5
Introduction.....	6
1 Scope	7
2 Normative references	7
3 Terms and definitions	8
4 Overview	10
4.1 General.....	10
4.2 Heat flux - energy balance on the sensor.....	10
4.3 Assumptions to achieve the required heat flux.....	11
5 Apparatus	12
5.1 Instrumented manikin.....	12
5.2 Posture of the manikin.....	15
5.3 Manikin sensors.....	16
5.3.1 Principle.....	16
5.3.2 Number of manikin sensors.....	17
5.3.3 Manikin sensor-measuring capability.....	18
5.3.4 Manikin sensor specification.....	18
5.3.5 Manikin sensor positioning.....	20
5.3.6 Manikin heat flux validation.....	20
5.4 Data acquisition system.....	22
5.5 Computer software program.....	22
5.5.1 General.....	22
5.5.2 Incident heat flux.....	23
5.5.3 Exposure heat flux.....	23
5.5.4 Thermal manikin protection factor (TMPF).....	23
5.5.5 Transferred energy.....	24
5.6 Flame exposure chamber.....	25
5.6.1 General.....	25
5.6.2 Chamber size.....	25
5.6.3 Chamber air flow.....	25
5.6.4 Chamber isolation.....	25
5.6.5 Chamber air exhaust system.....	25
5.6.6 Chamber safety devices.....	25
5.7 Fuel and delivery system.....	26
5.7.1 General.....	26
5.7.2 Fuel.....	26
5.7.3 Fuel delivery and shut-off system.....	26
5.7.4 Burner system.....	26
5.8 Image recording equipment.....	27
5.9 Safety checklist.....	27
5.10 Laboratory capability demonstration.....	28
6 Sampling and test specimens	28
6.1 General.....	28
6.2 Number of test specimens.....	28
6.3 Size of test specimen.....	28
6.4 Specimen preparation.....	29

6.4.1	Conditioning.....	29
6.4.2	Optional laundering.....	29
6.5	Standard reference garment design.....	29
7	Pre-requisites for products implementing this test method.....	30
8	Procedure.....	31
8.1	Preparation of test apparatus.....	31
8.1.1	General.....	31
8.1.2	Manikin sensor check.....	31
8.1.3	Flame exposure chamber purging.....	32
8.1.4	Confirming safe operation conditions and lighting of pilot flames.....	32
8.1.5	Gas line charging.....	32
8.1.6	Confirmation of nude and garment exposure conditions.....	32
8.2	Specimen testing procedure.....	33
8.2.1	General.....	33
8.2.2	Dressing the manikin.....	33
8.2.3	Recording the specimen identification, test conditions and test observations.....	34
8.2.4	Starting the image recording system.....	34
8.2.5	Setting time for heat transfer data acquisition.....	35
8.2.6	Exposure of the test specimen.....	35
8.2.7	Recording of specimen response remarks.....	35
8.2.8	Calculation of surface incident heat flux and transferred energy.....	35
8.2.9	Still images.....	35
8.3	Preparing for the next test exposure.....	35
9	Test report.....	36
9.1	General.....	36
9.2	Specimen identification.....	36
9.3	Exposure conditions.....	36
9.4	Results for each specimen.....	37
9.4.1	General.....	37
9.4.2	Heat flux data of each manikin sensor.....	37
9.4.3	Thermal manikin protection factor.....	37
9.4.4	Transferred energy.....	37
9.4.5	Other information that may be reported.....	38
9.5	Observations.....	38
	Annex A (informative) Considerations for conducting tests and using test results.....	39
	Annex B (informative) Interlaboratory test data analysis.....	40
	Annex C (normative) Calibration and validation procedure.....	42
	Annex D (informative) Burner stand alignment for flame engulfment.....	45
	Annex E (informative) Elements of a computer software program.....	48
	Bibliography.....	50