

ISO 28801:2011-03 (E)

Double sampling plans by attributes with minimal sample sizes, indexed by producer's risk quality (PRQ) and consumer's risk quality (CRQ)

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Terms, definitions, abbreviations and symbols		1
3 Choosing and operating a sampling plan		4
4 Operating characteristics		5
5 Average sample sizes		5
6 Actual producer's and consumer's risks		6
7 Average outgoing quality (AOQ)		6
8 Examples		7
9 Tables and figures		7
Annex A (informative) Statistical theory underlying the plans, tables and figures		63
Bibliography		70