

# ISO 28801:2011-03 (E)

Double sampling plans by attributes with minimal sample sizes, indexed by producer's risk quality (PRQ) and consumer's risk quality (CRQ)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Terms, definitions, abbreviations and symbols</b> .....		1
3 <b>Choosing and operating a sampling plan</b> .....		4
4 <b>Operating characteristics</b> .....		5
5 <b>Average sample sizes</b> .....		5
6 <b>Actual producer's and consumer's risks</b> .....		6
7 <b>Average outgoing quality (AOQ)</b> .....		6
8 <b>Examples</b> .....		7
9 <b>Tables and figures</b> .....		7
<b>Annex A (informative) Statistical theory underlying the plans, tables and figures</b> .....		63
<b>Bibliography</b> .....		70