

ISO 3951-4:2011-08 (E)

Sampling procedures for inspection by variables - Part 4: Procedures for assessment of declared quality levels

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Normative references		2
3 Terms, definitions, symbols and abbreviations		2
4 Principles		3
5 Declared quality level (DQL)		4
6 Sampling plans		5
7 Operating a sampling plan		8
8 Further information		15
Annex A (informative) Method of matching variables plans to attributes plans		20
Annex B (informative) Examples of use of the procedures		21
Bibliography		25