

# ISO 3951-4:2011-08 (E)

## Sampling procedures for inspection by variables - Part 4: Procedures for assessment of declared quality levels

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	2
3	Terms, definitions, symbols and abbreviations .....	2
4	Principles .....	3
5	Declared quality level (DQL) .....	4
6	Sampling plans .....	5
7	Operating a sampling plan .....	8
8	Further information .....	15
Annex A (informative) Method of matching variables plans to attributes plans .....		20
Annex B (informative) Examples of use of the procedures .....		21
Bibliography .....		25