

ISO 7870-6:2016-02 (E)

Control charts - Part 6: EWMA control charts

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Symbols and abbreviated terms	1
4	EWMA for inspection by variables	2
4.1	General	2
4.2	Weighted average explained	3
4.3	Control limits for EWMA control chart	4
4.4	Construction of EWMA control chart	4
4.5	Example	6
5	Choice of the control chart	9
5.1	Shewhart control chart versus EWMA control chart	9
5.2	Average run length	10
5.3	Choice of parameters for EWMA control chart	10
5.3.1	Choice of	10
5.3.2	Choice of L_z	11
5.3.3	Calculation for n	11
5.3.4	Example	12
6	Procedure for implementing the EWMA control chart	12
7	Sensitivity of the EWMA to non-normality	13
8	Advantages and limitations	13
8.1	Advantages	13
8.2	Limitations	13
Annex A (informative) Application of the EWMA control chart		14
Annex B (normative) EWMA control chart for controlling a proportion of nonconforming units		18
Annex C (normative) EWMA control charts for a number of nonconformities		20
Annex D (informative) Control chart effectiveness		22
Bibliography		26