

# DIN ISO 10004:2019-07 (E)

## Quality management - Customer satisfaction - Guidelines for monitoring and measuring (ISO 10004:2018)

---

| <b>Contents</b>   |   | <b>Page</b> |
|---|---|-------------|
| National foreword .....   |   | 4           |
| National AnnexNA (informative) Bibliography .....   |   | 5           |
| Foreword .....  |   | 6           |
| <b>A</b>  | <b>comma is used as the decimal marker. 7.6.3 Examining customer satisfaction information .....</b> | <b>21</b>   |
| <b>7.6.4</b>  | <b>Monitoring actions taken in response to customer satisfaction information .....</b>              | <b>21</b>   |
| <b>7.6.5</b>  | <b>Assessing the effectiveness of actions taken .....</b>   | <b>21</b>   |
| <b>8</b>  | <b>Maintenance and improvement .....</b>  | <b>22</b>   |
| <b>Annex A (informative) Interrelationship of ISO 10001, ISO 10002, ISO 10003 and this document</b> |   | <b>23</b>   |
| <b>Annex B (informative) Conceptual model of customer satisfaction .....</b>                        |   | <b>25</b>   |
| <b>Annex C (informative) Identification of customer expectations .....</b>                          |   | <b>27</b>   |
| <b>Annex D (informative) Direct measurement of customer satisfaction .....</b>                      |   | <b>30</b>   |
| <b>Annex E (informative) Analysis of customer satisfaction data .....</b>                           |   | <b>36</b>   |
| <b>Annex F (informative) Using customer satisfaction information .....</b>                          |   | <b>41</b>   |
| <b>Bibliography .....</b>   |   | <b>43</b>   |
| <b>7.4</b>  | <b>Analysing customer satisfaction data .....</b>   | <b>19</b>   |
| <b>7.4.1</b>  | <b>General .....</b>  | <b>19</b>   |
| <b>7.4.2</b>  | <b>Preparing the data for analysis .....</b>  | <b>19</b>   |
| <b>7.4.3</b>  | <b>Determining the method of analysis .....</b>   | <b>19</b>   |
| <b>7.4.4</b>  | <b>Conducting the analysis .....</b>  | <b>19</b>   |
| <b>7.4.5</b>  | <b>Validating the analysis .....</b>  | <b>20</b>   |
| <b>7.4.6</b>  | <b>Reporting results and recommendations .....</b>  | <b>20</b>   |
| <b>7.5</b>  | <b>Communicating customer satisfaction information .....</b>  | <b>20</b>   |
| <b>7.6</b>  | <b>Monitoring customer satisfaction .....</b>   | <b>21</b>   |
| <b>7.6.1</b>  | <b>General .....</b>  | <b>21</b>   |
| <b>7.6.2</b>  | <b>Examining the customers selected and the data gathered .....</b>                                 | <b>21</b>   |